

Tender No.400/2010/562/BYO/ISD dtd. January 04, 2010
Clarifications to Bidders queries

S. No	Rfp Clause No. & Reference	Bidder's query	SIDBI's Response
1	Annexure II(A), S.No. 4 - No. of populated cartridge slots.	Should be changed as Min. 48 or more. Scalable upto minimum 100 slots	No Change.
2	Annexure II(A), S.No. 8 - Cartridge backward compatibility.	Should be changed as LTO3 & LTO2.	No Change. As it is correctly mentioned as LTO-3 (Read/Write) and LTO-2 (Read).
3	Annexure II(B), S.No.6 - System Bus	Systems bus may be prescribed in terms of Intel QPI speeds	Agreed. Same should be read as 5.86 GT/s via Intel QuickPath Interconnect (QPI).
4	Annexure II(B), S.No.9 - Hard Disk Controller	Should be changed as Serial attached SCSI (SAS) Controller with high speed data transfer & Integrated Hardware RAID 0,1 support.	No Change.
5	Annexure III S.No.9 - Tape Library under buyback.	Is it possible to do the inspection of existing Tape Library for buy back.	Yes. Inspection with prior intimation to SIDBI may be done during 10:00 AM - 5:00 PM till January 27, 2010.
